Camp Pools

Camp Radford (CLOSED 1991) - Built 1962

San Bernardino Mountains

Capacity: 75 people



Camp Radford remains closed due to damage that occurred as a result of the Landers Earthquake in 1992. Plans for the Dining Hall / Kitchen renovation and the Lodge repair are completed. All modifications were recently approved by San Bernardino County Building and Safety and the Forest Service and include seismic and ADA improvements, water tank refurbishment, replacement of four cabins, pool replacement and restroom facility replacement. Funding is being sought.

#18 Priority for Replacement

Camp Seely – Built 1972

San Bernardino Mountains **Capacity:** 90 people



This pool and its equipment are in fair condition, with upgrades for ADA compliance necessary.

Camp Seely Pool - Immediate Repairs Needed				
1	Paint and caulk pool tank	\$45,000		
2	Paint interior and exterior of building	\$10,000		
TOTAL		\$55,000		

Camp Valcrest (CLOSED 1997) - Built 1945

Angeles National Forest Capacity: 105 people



Due to Camp Valcrest's proximity to the City of Los Angeles, it is a popular camp site, used for teen camping trips, day camp, overnight programs, and our winter and summer urban youth camping programs. The pool was closed due to a contaminated water supply. Additionally, the facility requires refurbishment, which includes a new fire alarm system for safety, a new pool building, bathhouse fencing and service road improvements, along with ADA upgrades.

#17 Priority for Replacement

Camp Pools-Continued

Griffith Park Boys Camp Pool – Built 1929

Capacity: 112 people



This pool was rebuilt in 1982 and is in good condition. It needs a chemical shed installed on the hillside between the filter room and the stairs.

Griffith Park Boys Camp Pool – Immediate Repairs Needed				
1	Paint interior and exterior of building	\$10,000		
2	Construct new pre-fab chemical room with retaining wall	\$125,000 BOE estimate		
TOTAL		\$135,000		

Hollywoodland Girls Camp Pool - Built 1951

Capacity: 172 people



This pool is in very poor condition. The pump and filter system were replaced in 1996, but the deck, pool tank, and retaining wall show cracks. The pool needs replacement, as do the restrooms which service the pool.

#16 Priority for Replacement