

INITIAL STUDY/NEGATIVE DECLARATION
MacArthur Park Band Shell Renovation Contract No. 2930

Prepared for:

City of Los Angeles
Department of Recreation and Parks
1200 W. 7th Street, Suite 700
Los Angeles, CA 90017

Contact: Paul Davis
213.928.9137

Prepared by:

Michael Brandman Associates
621 E. Carnegie Drive, Suite 100
San Bernardino, CA 92408

Contact: Kent Norton
909.884.2255



November 27, 2006

TABLE OF CONTENTS

Section 1: Introduction	1-1
1.1 - Purpose	1-1
1.2 - Project Location	1-1
1.3 - Project Description	1-1
1.4 - General History	1-17
1.5 - Environmental Setting	1-23
1.6 - Surrounding Land Uses	1-23
1.7 - Intended use of this Document	1-24
Section 2: Environmental Evaluation	2-1
2.1 - Background	2-1
2.2 - Environmental Factors Potentially Affected	2-2
2.3 - Environmental Determination	2-2
2.4 - impact terminology	2-3
2.5 - Environmental Checklist	2-3
Section 3: Discussion of Environmental Evaluation	3-21
I. Aesthetics	3-21
II. Agricultural Resources	3-22
III. Air Quality	3-23
IV. Biological Resources	3-26
V. Cultural Resources	3-28
VI. Geology and Soils	3-30
VII. Hazards and Hazardous Materials	3-33
VIII. Hydrology and Water Quality	3-36
IX. Land Use and Planning	3-39
X. Mineral Resources	3-41
XI. Noise	3-42
XII. Population and Housing	3-46
XIII. Public Services	3-47
XIV. Recreation	3-48
XV. Transportation/Traffic	3-50
XVI. Utilities and Service Systems	3-53
XVII. Mandatory Findings Of Significance	3-55
Section 4: References.....	4-1
Section 5: List of Preparers	5-1

LIST OF EXHIBITS

Exhibit 1: Regional Location Map..... 1-3
Exhibit 2: Local Vicinity Aerial Map 1-5
Exhibit 3: Local Vicinity USGS Map 1-7
Exhibit 4: Project Aerial Photograph 1-9
Exhibit 5: Existing Band Shell Floor Plan 1-11
Exhibit 6: Proposed Band Shell Floor Plan 1-13
Exhibit 7: Conceptual Landscaping Plan..... 1-15
Exhibit 8: Site Photographs..... 1-18

LIST OF TABLES

Table 1: Project Emissions and SCAQMD Thresholds 3-24

LIST OF APPENDICES

Appendix A: Air Quality Analysis